#### Global Crossing Telecommunications, Inc.

180 South Clinton Avenue Rochester, NY 14646 Tel +1.716.777.8497 Fax +1.716.546.7823





March 21, 2000

Mr. Dale Hatfield Chief, Office of Engineering and Technology Federal Communications Commission 2000 M Street, N.W., Suite 480 Washington, DC 20554

Re: Final FCC Service Disruption Report

Dear Mr. Hatfield:

As required by Section 63.100(a) of the Commission Rules, Global Crossing hereby files its Final Service Disruption Report for a Global Crossing network outage on February 23, 2000.

If you have any questions regarding this outage, please do not hesitate to call me.

Very truly yours,

Martin T. McCue

cc: Daniel Enright

Adrian VanBourgondien

mantinale

#### FINAL SERVICE DISRUPTION REPORT

DATE OUTAGE BEGAN:

02/23/2000

TIME OUTAGE BEGAN:

00:20 EST

DATE OUTAGE RESOLVED:

02/23/2000

TIME OUTAGE RESOLVED:

13:20 EST

GEOGRAPHICAL AREA OF OUTAGE: CENTRAL NEW YORK STATE

LOCATION: ROCHESTER, NEW YORK

NUMBER OF CUTOMERS OR CIRCUITS AFFECTED: Not Available

ESTIMATED # OF BLOCKED CALLS:

220,000

TYPE OF SERVICE AFFECTED: VOICE AND DEDICATED TRAFFIC

APPARENT OR KNOWN CAUSE OF THE INCIDENT:

The outage occurred when unknown parties started a fire in a structure under the Broad Street Bridge in Rochester, NY. The fire in the structure spread to the wooden roof. The heat from the roof burned the fiber cable that was 20 feet above the ground.

METHODS USED TO RESTORE SERVICE:

A section of fiber cable was replaced to restore service.

### STEPS TAKEN TO PREVENT RECURRENCE:

The fiber cable has been enclosed in hardened conduit to make it less susceptible to outside forces.

#### ANALYSIS OF EFFECTIVENESS OF BEST PRACTICES:

6.1.3 Details – Key Lessons Learned and Best Practices.

The affected fiber routing was reviewed and it was installed per established best practices.

## 6.1.4 Effective Countermeasures

Global Crossing has established training programs used to keep personnel up to date and knowledgeable in fiber optic maintenance and restoration.



00-23

Global Crossing Corporation Network Operations Center Southfield, Michigan (888) 907-6638

Adrian VanBourgondien, Director (248) 223-1324

INITIAL SERVICE DISRUPTION REPORT

DATE OUTAGE BEGAN ...... 02/23/2000 TIME OUTAGE BEGAN ..... 00:20 EST

DATE OUTAGE RESOLVED......: 02/23/2000 TIME OUTAGE RESOLVED.....: 13:20 EST

GEOGRAPHICAL AREA OF OUTAGE: CENTRAL NEW YORK STATE

LOCATION: ROCHESTER, NEW YORK

NUMBER OF CUTOMERS OR CIRCUITS AFFECTED: UNKNOWN

ESTIMATED # OF BLOCKED CALLS: 90,000 +

TYPE OF SERVICE AFFECTED....: VOICE AND DEDICATED TRAFFIC

APPARENT OR KNOWN CAUSE OF THE INCIDENT: UNDER INVESTIGATION

METHODS USED TO RESTORE SERVICE: SPLICED FIBER

STEPS TAKEN TO PREVENT RECURRENCE: UNDER REVIEW

FRONTIER

00-23

→→→ CCB

# FCC INITIAL SERVICE DISRUPTION REPORT

¥	In co Telep 3.0	mpliance with Federal Communications Commission Regulation 63.100, Frontier phone of Rochester hereby notifies the FCC of the following service disruption: This outer to cold ISSUE. This affects FCT (long distance Date and estimated time event started:
		2/23/00 approx. 1:00 Am
	<b>2</b> .	Geographic area affected:
		any long distance Customer where PIC is FI
	3.	Estimated number of customers affected: TBD
	4.	Type(s) of service(s) affected: durines on FCI hetwork such together, wegmans in Buffelo, typecuse + PA.  Duration of outage:
	5.	Opprox, time of restration 2/23/00 1:30pm
	6.	Estimated number of blocked calls during the outage:
	7.	Apparent or known cause of incident: Cable fire in xuberray between Broad It. and Exchange At.
-	8.	Methods used to restore service: The damaged distrion was cut out and film was replaced.
	9.	Steps taken to prevent recurrences: TBD
TBD - If used above, indicates that the indetermined.		If used above, indicates that the information is unknown at this time and is to be nined.
	A final	Service Disruption Report will be provided within 30 days.
This report is sent by Deb Fasciano		eport is sent by: Deb Fasciano who can be
	reached at (716) 777-5823	
		ent: 2/23/00 Time sent: /:30 pm